

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: August 2026

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of August 21st

Non-Compliances/AWQI: None

Equipment Issues:

- Replaced batteries in PLC UPS at Huronville South
- Corrected analyzer flow issues at Murdoch Glen
- Repaired leaking chlorine board at Murdoch Glen
- Corrected analyzer flow issues at Huronville South
- Repaired leaking chlorine board at Huronville South
- Repaired faulty Tachmina in Huronville South

Planned Maintenance:

- Annual backflow device inspections completed
- New service connection at 20 Penetangore Row S (private side)
- New service connection at 16 Penetangore Row S (private side)
- New service connection at 14 Penetangore Row S (private side)

Main breaks and Leaks/Repairs:

- Emergency shut off for 915 Greg's Trail (leak on private side)
- Emergency shut off for 28 Touts Grove Hill (leak on private side)
- Leaking service repaired at 5 Sunset Pl (vacant lot)
- Repaired watermain break across from 905 Cedar Trail

Power Outages: None

Complaints / Requests:

- Rusty water complaint at 216 Gregor Dr (collected iron samples)

Locates: (see Township master list)

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of August 21st

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired leaking chlorine board at Well 4

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

- Repaired faulty Tachmina at Well 4

Planned Maintenance:

- Annual backflow device inspections completed
- New service connection at 661 Havelock

Main breaks and Leaks/Repairs:

- Emergency shut off for 561 Victoria st (leak on private side)

Power Outages: None

Complaints / Requests:

- Yellow water complaint at 1142 Amberley Rd (flushed watermain)
- Yellow water complaint at 310 Ross st (flushed watermain)

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of August 21st

Non-Compliances/AWQI: None

Equipment Issues:

- Uncommanded start/stop alarm condition for HLP1 corrected
- WP3 fail to stop issue corrected

Planned Maintenance:

- Annual backflow device inspections completed
- Replaced batteries on Fire Hall generator

Main breaks and Leaks: None

Power Outages:

- Brief outage at the reservoir on August 4th due to a tripped main breaker

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of August 21st

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired leaking chlorine pump
- Replaced failed UPS battery for communications equipment

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Planned Maintenance:

- Annual backflow device inspections completed

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances: None

Equipment Issues/Incidents:

- Continued diverting aerated lagoon flow to the storage lagoon. Received approval from MECP Inspector and met with BM Ross on October 31st to discuss possible solutions for poor drainage. Test holes dug on November 20th. Sourcing materials for filter rebuild
- Cleaned out interconnect chambers at the Lagoon
- Contacted OPP about drug paraphernalia left at the SPS on Friday August 14th (items removed by OPP)

Planned Maintenance:

- Annual backflow device inspections completed
- New service connection at 661 Havelock

Sewer Main Breaks and Leaks: None

Power Outages: None

Total Locates: (see Township master list)

RIPLEY

Exceedances: None

Non-Compliances: None

Equipment Issues: None

Planned Maintenance:

- Annual backflow device inspections completed
- Septage receiving station installed at the SPS

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

- Maintenance hole inspections ongoing

Sewer Main Breaks and Leaks: None

Power Outages: None

Complaints: None

Total Locates: (see Township master list)

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark
- Repair PSV on Concession 8

Ripley

- HLP piping replacement in the Ripley wellhouse.

Lucknow

- Piping replacement in Well 4
- Chlorine pump upgrades in Well 4
- Auto-flusher installation on South Delhi

Whitechurch

- Pressure tank replacements x2
- Chlorine pump upgrades

WASTEWATER:

Lucknow:

- RIB media replacement
- Lagoon cell sludge removal

Ripley: None