

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: July 2026

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of July 24th

Non-Compliances/AWQI:

- AWQI# 173299 in Point Clark for Sodium exceedance (resampled)
- AWQI# 173300 in Blairs Grove for Sodium exceedance (resampled)
- AWQI# 173301 in Murdoch Glen for Sodium exceedance (resampled)
- AWQI# 173302 in Huronville South for Sodium exceedance (resampled)

Equipment Issues:

- Repaired faulty Tachmina in Point Clark
- Repaired leaking chlorine board in Point Clark
- Repaired leaking sodium silicate pump at Murdoch Glen
- Repaired leaking chlorine analyzer at Blairs Grove
- Repaired leaking chlorine analyzer at Huronville South

Planned Maintenance:

- Quarterly meter reads completed
- Collected Iron and Manganese samples
- Collected Sodium Samples
- Collected Quarterly samples
- Resampled for Sodium exceedances
- New watermain commissioned and connected to existing system on Boiler Beach and Penetangore Row S
- New service connection at 955 Bogdanovic (private side)
- New service connection at 616 Potawatomi (private side)

Main breaks and Leaks/Repairs:

- Leaking service for 48 Penetangore Row S replaced (private side)
- Repaired broken curbstop for 218 Gregor (new cap)

Power Outages: None

Complaints / Requests:

- Low pressure complaint at 868 Lake Range due to tie-in on Boiler Beach and Huronville being isolated (June 30th)
- Intermittent pressure loss complaint at 74 Vozka (private plumbing issue).

Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of July 24th

Non-Compliances/AWQI: None

Equipment Issues:

- Repaired leaking chlorine board at Well 4
- Repaired faulty Tachmina at Well 4
- Elevated tank/SCADA communications issues resolved
- Repaired leaking POE chlorine analyzer in Well 5

Planned Maintenance:

- Quarterly meter reads completed
- Collected Sodium samples
- Collected Quarterly samples
- Replaced pre-contact chlorine analyzer in Well 5
- MECP Inspector on-site for unannounced annual inspection (July 16th)
- Landmark completed tower venting rust remediation

Main breaks and Leaks/Repairs:

- Emergency shut off for 661 Havelock (house demolished)
- New curbstop installed at 732 Stauffer

Power Outages:

- Short outage on July 1st

Complaints / Requests:

- Rusty water complaint at 370 S Delhi st (flushed watermain)

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of July 24th

Non-Compliances/AWQI:

- AWQI#173297 at the Wellhouse for Sodium exceedance (resampled)
- AWQI#173298 at the Elevated Tank for Sodium exceedance (resampled)

Equipment Issues:

- Replaced leaking chlorine injector for Well 3

Planned Maintenance:

- Quarterly meter reads completed

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

- Conducted Elevated Tank drawdown test
- Collected Sodium samples
- Collected Quarterly samples
- Resampled for Sodium exceedances
- Replaced pre-contact chlorine analyzer at the Elevated Tank
- Temporary watermain commissioning and tie-in to existing system completed for Park st reconstruction project.

Main breaks and Leaks:

- Leaking service repaired and seized curbstop replaced at 4 William

Power Outages:

- Short outage on July 1st

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of July 24th

Non-Compliances/AWQI: None

Equipment Issues: None

Planned Maintenance:

- Collected Quarterly samples
- Annual generator service completed
- Replaced pre-contact chlorine analyzer

Main breaks and Leaks: None

Power Outages:

- Brief outage for annual generator service/test (July 3rd)

Complaints / Requests: None

Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances: None

Equipment Issues:

- Continued diverting aerated lagoon flow to the storage lagoon. Received approval from MECP Inspector and met with BM Ross on October 31st to discuss possible solutions for poor drainage. Test holes dug on November 20th. Sourcing materials for filter rebuild

Planned Maintenance:

- Annual generator service completed
- New alum pump installed at the Lucknow Lagoon
- Alum delivery received at the Lucknow Lagoon

Sewer Main Breaks and Leaks: None

Power Outages:

- Short outage on July 1st
- Brief outage for annual generator service/test (July 3rd)

Total Locates: (see Township master list)

RIPLEY

Exceedances: None

Non-Compliances: None

Equipment Issues: None

Planned Maintenance:

- Alum delivery received at the Ripley SPS

Sewer Main Breaks and Leaks: None

Power Outages:

- Short outage on July 1st

Complaints: None

Total Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark
- Repair PSV on Concession 8

Ripley

- HLP piping replacement in the Ripley wellhouse.

Lucknow

- Piping replacement in Lucknow well 4

Whitechurch

- Pressure tank replacements x2

WASTEWATER:

Lucknow: None

Ripley: None